
LEAD FREE COMPRESSION

LEAD FREE BRASS FITTINGS

LEAD FREE

BRASS COMPRESSION FITTINGS - LEAD FREE

- Three piece construction- nut, sleeve (or ferrule) and body
- Use with copper, aluminum, or plastic tubing (plastic requires 60P sleeve and 61P insert)
- -40° to +250° F. temperature range
- · Easy to disassemble, no flaring tool required
- Primary uses: water, gasoline, oil, and vacuum lines



TO ASSEMBLE:

- 1 Cut smooth, square end on tubing
- 2 Slide nut, then sleeve onto tube. Threads must face end
- 3 Insert tube into fitting
- 4 Thread nut onto fitting until snug, then as follows:

Tube O.D.	1/8	3/16	1/4	5/16	3/8	7/16	1/2	5/8	3/4	7/8
Thread Size	5/16-24	3/8-24	7/16-24	1/2-24	9/16-24	5/8-24	11/16-20	13/16-18	1-18	1-1/8-18

BRASS COMPRESSION FITTINGS

BRASS SLEEVE



LF260
• FERRULES

PART #	SIZE	LIST
700060-02	1/8"	
700060-03	3/16"	
700060-04	1/4"	
700060-05	5/16"	
700060-06	3/8"	
700060-07	7/16"	
700060-08	1/2"	
700060-10	5/8"	
700060-12	3/4"	
700060-14	7/8"	

60 260

DELRIN SLEEVE



PART #	SIZE	LIST
00560-04	1/4"	;; ;
00560-05	5/16"	
00560-06	3/8"	
00560-08	1/2"	
00560-10	5/8"	()

60-P



Sales@MidlandIndustries.com

Fax 1-800-877-5391