## **Gruvlok® High Pressure Systems**





The Gruvlok Fig. 7004 is designed to provide the versatility of a grooved joint while providing a rigid pipe joint.

The Fig. 7004 coupling permits working pressure ratings up to 1200 psi (82.7 bar).

This coupling is also suited for lower pressure systems which experience pressure pulses. Systems used for high pressure, including auto and truck washes, will benefit from the increased pressure capability.

Working Pressure & End Load values are based on grooved standard wall pipe.

Fig. 7004 provides a rigid joint and does not allow for expansion or contraction. The Fig. 7004 coupling is an ideal choice for higher pressure applications such as elevator services.

**Note:** Fig. 7004 can be used with EG fittings as a commercial joint only.

### **Material Specifications**

### Bolts

SAE J429, Grade 5, Zinc Electroplated ISO 898-1, Class 8.8, Zinc Electroplated followed by a Yellow Chromate Dip

#### **Heavy Hex Nuts**

ASTM A563, Grade A, Zinc Electroplated ISO 898-2, Class 8.8, Zinc Electroplated followed by a Yellow Chromate Dip

### Stainless Steel Bolts & Nuts

304SS bolts and nuts are available as a standard option. (316SS are available for special order)

Housing Ductile Iron conforming to ASTM A 536, Grade 65-45-12.

### **Material Specifications (continued)**

### Coatings

Rust inhibiting paint Color: Orange (standard) Hot Dipped Zinc Galvanized (optional) Other Colors Available (IE: RAL3000 and RAL9000)

For other Coating requirements contact an ASC Engineered Solutions™ Representative.

#### **Gasket Materials**

Properties as designated in accordance with ASTM D2000 Grade "EP" EPDM (Green and Red color code) Standard -40°F to 250°F (Service Temperature Range) (-40°C to 121°C)

Recommended for water service, diluted acids, alkalies solutions, oil-free air and many other chemical services. NOT FOR USE IN PETROLEUM APPLICATIONS.

For hot water applications the use of Gruvlok Extreme Temperature lubricant is recommended.

Grade "T" Nitrile (Orange color code) -20°F to 180°F (Service Temperature Range) (-29°C to 82°C)

Recommended for petroleum applications. Air with oil vapors and vegetable and mineral oils. NOT FOR USE IN HOT WATER OR HOT AIR.

Grade "O" Fluoro-Elastomer (Blue color code) Size Range: 2" - 12" (C style only) 20°F to 300°F (Service Temperature Range)

(-29°C to 149°C)

Recommended for high temperature resistance to oxidizing acids, petroleum oils, hydraulic fluids, halogenated hydrocarbons and lubricants.

**Grade "L" Silicone** (Red color code) Size Range: 2" - 12" (C style only)

-40°F to 350°F (Service Temperature Range) (-40°C to 177°C)

Recommended for dry, hot air and some high temperature chemical services.

### Gasket Type

Standard C Style (2" - 12") Flush Gap (2" - 12")

Lubrication

Standard Gruvlok Gruvlok Xtreme (Do Not use with Grade "L")

### Working Pressure, End Load, Pipe End Separation &

**Deflection from Center Line** Based on standard wall steel pipe with cut or roll grooves in accordance with Gruvlok specifications. See technical data section for design factors.




PROJECT INFORMATION	APPROVAL STAMP
Project:	Approved
Address:	Approved as noted
Contractor:	Not approved
Engineer:	Remarks:
Submittal Date:	
Notes 1:	
Notes 2:	

# **Gruvlok® High Pressure Systems**



## Coupling Fig. 7004






Fig. 7004 with Standard Gasket

Nominal Size	0.D.	Max. Wk. Pressure †	Max. End Load	Range of Pipe End Separation	Coupling Dimensions			Coupling Bolts		Approx.
					Х	Y	Z	Qty.	Size	Wt. Ea.
In./DN(mm)	In./mm	PSI/bar	Lbs./kN	In./mm	In./mm	In./mm	In./mm		In./mm	Lbs./kg
2	2.375	1200	5,316	0-1/32	35/8	61⁄4	1 7/8	2	<sup>5</sup> ∕8 x 2³∕₄	3.9
50	60.3	82.7	23.6	0-0.79	92	159	48	Ζ	-	1.8
21/2	2.875	1200	7,790	0-1/32	41⁄4	67/8	1 7/8	2	5∕8 X 31⁄2	4.6
65	73.0	82.7	34.7	0-0.79	108	175	48	Ζ	M16 x 85	2.1
3	3.500	1200	11,545	0-1/32	47/8	71/2	1 7/8	2	5∕8 x 31⁄2	5.2
80	88.9	82.7	51.4	0-0.79	124	191	48	Z	M16 x 85	2.4
4	4.500	1200	19,085	0-3/32	61⁄4	91/2	21/4	0	<sup>3</sup> / <sub>4</sub> x 4 <sup>1</sup> / <sub>2</sub>	8.6
100	114.3	82.7	84.9	0-2.38	159	241	57	2	M20 x 110	3.9
5	5.563	1000	24,306	0-3/32	71/2	11	21/4	2	7∕8 x 5½	14.0
125	141.3	68.9	108.1	0-2.38	191	279	57	Ζ	M22 x 150	6.4
6	6.625	1000	34,472	0-3/32	8 3/4	121/8	21/4	2	7∕8 x 5½	15.5
150	168.3	68.9	153.3	0-2.38	222	308	57	Ζ	M22 x 150	7.0
8	8.625	800	46,741	0-3/32	111/8	141/8	25/8	2	1 x 5½	25.6
200	219.1	55.2	207.9	0-2.38	283	378	67		-	11.6
10	10.750	800	72,610	0-3/32	13½	17	25/8	2	1 x 6½	32.3
250	273.1	55.2	323.0	0-2.38	343	432	67	Ζ	_	14.7
12	12.750	800	102,141	0-3/32	151/8	19¼	25/8	2	1 x 6½	43.9
300	323.9	55.2	454.4	0-2.38	403	489	67	2	-	19.9

### Note:

+ Maximum Working Pressure Rating is for schedule 40 steel pipe. For light wall, stainless steel, aluminum and ISO pipe pressure ratings, please refer to the technical data section. For additional details see "Coupling Data Chart Notes" in the Introduction Section of the Gruvlok Catalog.

See Installation & Assembly directions on next page.

Not for use in copper systems.




asc-es.com

## Building connections that last




## Fig. 7004 Coupling



WARNING Ensure system is drained and depressurized before

installation or service.





Failure to follow these instructions could result in serious personal injury and/or property damage.

#### Check & Lubricate Gasket 1

Check gasket to be sure it is compatible for the intended service. Apply a thin coat of Gruvlok Lubricant to the exterior surface and sealing lips of the gasket. Be careful that foreign particles do not adhere to lubricated surfaces.

### 2 Gasket Installation

before use.

Slip the gasket over the pipe end, making sure the gasket lip does not overhang the pipe end.

## 3 Alignment

After aligning the two pipe ends together, pull the gasket into position, centering it between the grooves on each pipe. Gasket should not extend into the groove on either pipe.

### 4 Housings

Place each housing halves on the pipe making sure the housing key fits into the groove. Be sure that the tongue and recess portions of the housing mate properly. Insert the bolts and run up the nuts finger tight.

## 5 Tighten Nuts


Securely tighten nuts alternately and equally to the required indicator. For 2" - 4" 7004 couplings, please use the table below for required torque values. For 7004 5" and larger, tighten nuts till housings are in metal-to-metal contact.

## 6 Assembly is Complete

Visually inspect the pipe joint to assure the coupling keys are fully engaged in the pipe grooves. For 2" - 4", ensure the gaps on each side are evenly spaced, and for 5" and larger couplings ensure the housings are in firm even metal-to-metal contact on both sides.







\* Torque required to bring housing metal-to-metal contact.

Caution: When using an impact wrench, verify that the output of the impact wrench is within the required torque range. It is recommended that a torque wrench be used for accurate assembly in order to obtain specified performance.



asc-es.com

Building connections that last<sup>\*\*</sup>